

Pair of connection adapters for GMH 3810 / GMR 110 handheld meters

GAD 3810[-38]

Introduction

For connection to GMH 3810 / GMR 110 instruments, the adapter family uses an M6 device-side connection. On the sensor side, each version provides banana sockets for connecting the GMK 3810 cable, plus an M8 thread for direct connection of compatible measuring accessories.

GAD 3810-38 is designed with an M8 x 1 sensor connection for GMS 300/38 measuring rods or GOK 38 surface caps. GAD 3810 uses an M8 x 1.25 sensor connection for GMS 300/91 measuring rods or GOK 91 surface caps.

Features

Device-side connection

M6 for connection to GMH 3810 / GMR 110.

Sensor connection

- Both versions: Banana sockets for connection of GMK 3810 cable.
- **GAD 3810:** M8 x 1.25 for direct connection of GMS 300/91 measuring rods or GOK 91 surface caps.
- **GAD 3810-38:** M8 x 1 for direct connection of GMS 300/38 measuring rods or GOK 38 surface caps.

Available product variants

Ordercode	Description	Article No.
GAD3810-38-GN	M8 x 1 for GMS 300/38 or GOK 38 - For direct connection of GMS 300/xx measuring rods or GOK xx surface caps to GMH 3810 / GMR 110 instruments.	484565
GAD3810-GN	M8 x 1.25 for GMS 300/91 or GOK 91 - For direct connection of GMS 300/xx measuring rods or GOK xx surface caps to GMH 3810 / GMR 110 instruments.	603232